



Application Specification

Elasta-Vistic Membrane Sound & Vibration Dampening

Purpose and Scope

To outline instructions for application of Elasta-Vistic Membrane A 100% solids, 0 VOC, sound and vibration dampening, epoxy resin base interior deck covering underlayment designed for application under all types of deck covering materials.

Thickness

Standard 40 mils DFT, maximum 125 mils DFT

Approximate Quantity of Materials Required

To Cover ONE HUNDRED SQ. FT (9.3 sq. Meters)

Thickness
1/6 inch (1 mm)

TM Boncoat
Component A (1 Gal..... 0.33units
Component B (1 Qrt)

Elasta-Vistic Membrane
Component A (5 Gal) 1.4 units
Component B (1 Gal)
Component C Aggregate (17 lb bag)

Equipment Required

- Dex-O-Tex Mixing Blade mounted in slow speed (275 RPM), 3/4" (19 mm) drill
- Mixing Container(s) (metal recommended over PVC)
- Jiffy Blade, (small size)
- Roller Frames and Handles
- 3/8" Nap Roller Covers
- Paint Brushes
- 1/4" X 1/4" "V" Notched Trowel
- Steel Trowel, (3" x 12"), (8 cm x 30 cm)
- Plasterer's Steel Trowel, (4" x 16"), (10 cm x 40 cm)
- Spiked Roller
- High Intensity Lighting, preferably deck level
- Approved solvent for cleaning tools
- All required Personnel Protective Equipment, gloves, safety glasses, hand cream, etc.

Surface Preparation

METAL: Deck surfaces shall be prepared in accordance with SSPC SP 11, to remove all mill scale, rust, paint, etc., to gray steel or as specified. Surface should be dry and free of rust, dirt, oil or grease.

Decks that have been cleaned and primed with Navy Formula 150 Primer, MIL-DTL-24441, EURONAVY ES301K Primer, or Pre-Construction Primer (PCP, Zinc Silicate), may be high-pressure water jet cleaned, and prepared in accordance with SSPC SP 1 and allowed to dry completely before application if practical within the space.. If any rusting is evident, prepare in accordance with SSPC SP 3 and SP 1; do not proceed with application until approved by supervising authority.

Material Temperature

The temperature of the materials should be between 65°F to 80°F (18°C to 29°C) for best mixing and application properties.

Ambient Temperature

For best working properties the ambient room temperature should be between 65°F to 80°F (18°C to 24°C). However, VLW can be installed in ambient temperatures as low as 55°F to as high as 100°F. However, workability will be adversely affected. A minimum temperature of 55°F and maximum temperature of 100°F must be maintained during and for at least 24 hours after application for proper curing.

Substrate Temperature

Deck surface and room temperature of 65°F to 80°F (18°C to 24°C) should be maintained for at least 24 hours prior to and after installation for proper curing.



Application Specification

Elasta-Vistic Membrane Sound & Vibration Dampening

APPLICATION

STEP ONE – Bondcoat

TM Bondcoat

Mix Ratio: 2A:1B Pot Life: 35 min
Cure Time: 6 hrs Recoat Time: 6-48 hrs.
Coverage: 225 sq. ft. DFT: 7 mils

A. Mix together the following materials:

TM Bondcoat Comp A (2 Parts by Volume)
TM Bondcoat Comp B (1 Part by Volume)

Measure out the required amount of Component A and Component B and pour into a clean mixing container, scraping the sides and bottom of cans to insure all materials are used. Mix with a low speed electrical mixer for approximately three minutes to a homogenous blend.

B. Apply a thin coat of TM Bondcoat using a trowel, squeegee, or roller over the area to be coated. Do not allow primer to puddle or be applied too thick. A one Gallon Kit (1 gal can A: 1 quart can B) mixture should cover approximately 225 square feet (225 sq. ft. / mixed gallon) over smooth surface. If surface is very porous, two coats may be required. Allow to cure before proceeding with the application.

STEP ONE – Bondcoat

Elasta-Vistic SVD Membrane

Mix Ratio: Do Not Split Pot Life: 35 min
Cure Time: 18 hrs Recoat Time: 18 – 48 Hr
Coverage: 40 sq. ft. DFT: 40 mils (Standard)

A. Mix together the following materials:

Elasta-Vistic Membrane Resin Comp A
(4 Parts by Volume)
Elasta-Vistic Membrane Resin Comp B
(1 Part by Volume)
Elasta-Vistic Membrane Powder Comp C

- B. Pour the contents of the can containing Elasta-Vistic SVD Membrane resin binder component B into the pail containing component A. Blend thoroughly to a homogenous mixture with a power drill motor and jiffy type mixing blade for approximately 2 minutes. Then slowly add the powder component C while continuing to mix. Mix for an additional 2 minutes after all the powder has been added. Inspect the mixed material to verify it is well mixed with no unmixed lumps or striations. Allow the mixed material to set a few minutes to allow any excess entrapped air to migrate out of the material.
- C. Pour the mixed Elasta-Vistic Membrane onto the primed deck and spread it out evenly over the surface with a 1/4" V-notch trowel. Trowel the material out in all directions to produce an even surface and allow material to self-level.
- D. A 5-gallon unit of Elasta-Vistic SVD Membrane mix will cover approximately 200 square feet of decking area at 40 mils thickness.
- E. After material has been applied, and flowed out, backroll the wet basecoat with a spiked roller to allow entrained air or gasses to escape. Continue rolling over the basecoat until it levels out and the occurrence of bubbles has dissipated.

Cautions

1. For proper workability it is important the Dex-O-Tex materials be stored and mixed at a temperature of 65°F-80°F.
2. The substrate temperature should be between 65°F-80°F. A warm substrate will decrease the pot life and make the material sticky. A cooler substrate will retard the cure and may cause a blush of the polymeric resins. Deck surface and room temperature of 65°F or slightly higher must be maintained for proper curing.
3. When mixing the polymeric resin components, be sure to use all of the provided resins. The resins are pre-measured to the correct ratios.



Application Specification

Elasta-Vistic Membrane Sound & Vibration Dampening

Scrape all of the hardener from the container into the resin.

4. Do not turn mixing vessels upside down to drain on the flooring surface. Unmixed resin from the side may produce soft or uncured spots on the flooring surface.
5. Keep the unfinished flooring surface clean. Do not track dirt, grease, or any other contaminate onto the unfinished flooring.
6. Good ventilation must be provided during application, particularly in confined spaces.
7. Always obtain, read and observe Manufacturers Safety Data Sheets (MSDS) before handling polymeric materials. Become familiar with the products on paper before you open the cans.

General Conditions for Safe Handling of Polymeric Resinous Flooring Systems

1. Read and observe precautionary statements on product labels.
2. Keep containers tightly closed.
3. Keep out of reach of children.
4. For industrial use only. Do not allow application by untrained workers.
5. Remove contaminated clothing and shoes. Wash clothing before re-use.
6. Use of safety goggles and chemical resistant gloves is recommended. Wear only full-length trousers and long-sleeve shirts. Apply protective creams to exposed skin areas.
7. In general, prolonged contact of polymeric resins with skin may cause irritation. Contact with curing agents may cause skin burns. Products may cause skin sensitization or other allergic responses. Avoid all contact with eyes.
8. In case of contact with skin, immediately remove the material with soap and water. Upon completion of work at lunchtime or end of day, carefully check all skin surfaces for any traces of polymeric resins. Wash with soap and water. If wash facilities are not located nearby, establish water-washing station at work site. DO NOT use solvents to remove polymeric resins from skin, as

solvents will drive polymeric resins deeper into skin. If redness or skin rash develop, consult a physician.

9. In the event of eye contact, flush immediately with plenty of water for at least 15 minutes. Consult a physician immediately.
10. Mix and apply polymeric resin materials only in conditions of good ventilation. Avoid breathing vapors. A fan to circulate fresh air may be needed. Certain polymeric resin products and/or certain working conditions require use of NIOSH/MSA organic vapor respirator. Consult MSDS.
11. First Aid for inhalation: if effects occur, remove patient to fresh air. If not breathing, give artificial respiration, preferably mouth-to-mouth. If breathing is difficult, give oxygen. Get immediate medical attention.



DOT MARINE PRODUCT LINE Crossfield Products Corp.

West Coast Office
3000 E. Harcourt Street
Rancho Dominguez, CA
90221
310-886-9100
310-886-9119 fax

East Coast Office
140 Valley Road
Roselle Park, NJ
07204
908-245-2800
908-245-0659 fax

www.dexotexmarine.com